Date: User: Thursday, 1/5/2006 7:09:42 AM

Linda Lacelle

Process Sheet

Customer

: CC-DAR01 Dart Aerospace Ltd.

Job Number : 25399

Estimate Number : 10804

P.O. Number

: N/A

This Issue Prsht Rev.

: 1/5/2006

: NIA First Issue : 00015

: NC

S.O. No. : N/A : NA **Part Number**

: K10005 : K10005

Drawing Number Project Number

Drawing Name

A14:

: RTN 438

Drawing Revision Material

Due Date

: 1114 HIN:

: 1/12/2006

Qty:

1 Um:

Each

Previous Run Written By

SEE ABOVE DATE & USER SER ABOVE DATE & USER

Checked & Approved By

Comment

Additional Product

Job Number:



Seq. #:

Machine Or Operation:

Description:

INSPECT WORK TO CURRENT STEP

1.0 QC5

Comment: INSPECT RTN 438

2.0

PACKAGING 1

PACKAGING RESOURCE #1

Comment: PACKAGING RESOURCE #1

REPACKAGE PER PPP

INSPECT KITS FOR COMPLETENESS & RECORD BATCH NUMBERS OF ALL PARTS:

4-X-D2182B050__B

8 X D2274

2 X D2671

4 X D2438 8 X D2529

8 X AN4-15A

8 X AN4-17A

16 X AN960JD416 B 8 X MS21042L4

2 X QS200M44S B

1 paper work from blue file Klosos

DC 3.0



Comment: DOCUMENT CONTROL

INSPECT LEVEL 21

5 41 06/01/13

Job Completion



5/19

DART AEROSPACE LTD	Work Order:	2 30 76
Description: Bearpaw Kit (13" x 16")	Part Number:	K10005
Dwg : D2671 Rev. B1	Qty:	5 Kits
Ref: K10005 Rev. A; DSK086-1 Rev. A		Page 1 of 1

Step	Location	Procedure	Ву	Date	Qty
1	DC	Issue Traveler	11		
	ļ	Note: (1) K10005 Kit consists of Qty (2) D2671	1981	05.04.19	5
2	DC	Dwg not required Photocopy bluefile: K10005	10		
		D206-559-021 NK 17			
		D500-572-021	POH	05.04.21	5
		and create labels per PPP K10005 CHG002	1	0 10 (.0)	
3	GA	(Bag Bluefiles separately)			
	GA	Cut 2 blanks per (1) K10005 Kit Cut blank: 13.25" x 16.00" x 1.00" thick (+0.030/-0.000) per			
		DSK086-1			
		Material: Black UHMW 1"	7.1		
	100	(MUHMWB10) Batch: B17736	118	0406/02	5
4	MV	Inspect material for defects or damage prior to machining	my	helocho	<i>5</i>
5	MV	Machine as per Folio and Dwg D2671 Pwg (ex B	D.	13 00,70,0	
		Identify as D2671 Filis (Lew_BL)	STOP	05/06/03	5
6	QC2	Inspect parts as they come off the CNC machine	The	05/06/03	5
7	MV	Deburr SD	In s	25/11/1/2	5
8	QC8 & 5	Second inspection	50	05.06.04	5
9	KP	Pick: Packing Kit (Note: D2671 is on the BOM as material		C5.00.03	
		from step 3)			İ
	•	Oty Part-Number Description Batch 4 D2182B050 Rubber Cushion F21872			
-		8 D2274 Radius Block B 22494			
		2 D2671 Bearpaw / 1523076	**	* *	
		4 D2438 Clamp 522503			
		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
		8 AN4-17A Bolt 1711/4526			[
	1	N6 AN960JD416 Washer M16941			
	,	8 MS21042L4 Nut (or -4) <u>117/5924</u>			
		-2 QS200M44S Clamp <u>YA16Q2O</u>	. ^		İ
		Paperwork package from Step 2	CX	05/06/07	5
10	QC4	Inspect Kit for 100% Completeness on the W/O	58	05/06/07	5
11	PK	Identify and pack for shipping as per PPP K10005	C.L	05/6/19	5
12	AC		. 1		
		Cost / part 155.53	A	05/06/13	5
13	DC	Close W/O /60.50 Inspect Level 21	d()	05,06.14	5

 Rev
 Date
 Change
 Revised By
 Approved

 A
 99.12.17
 K10005 created for Bearpaw Kit
 EC

 B
 03.05.28
 Reformat; Incorporated D2671
 KJ/RF

 C
 04.02.17
 Blank size changed
 KJ/JLM

A 106/10

DELEASEN